

Release note

LinkCom 5 S and LinkCom 5 M

Versions: S80 652.060 and S80 656.060, August 10, 2018

Corrections

- Fixed issue with long replacement strings that caused the LinkCom PrintServer to hang due to insufficient data buffer allocation.
- Manual change of subnet mask was overruled back to 255.255.255.0 after a restart
- Default output accidentally set to USB (for the LinkCom 5 S edition). Corrected to default network output with autodetect printer.
- Default IPDS setting changed from IBM4028/PCL5 to IBMIP40/PS.
- Updated IPDS fontset added.
- Modified configuration of DNS server entry on webpage.

Known issues

- LinkCom 5 needs about 2 minutes to complete the power up process before the test button can be pressed. Pressing the test button too early may cause the test print to be delayed or not printed at all.

Concern

Replaces earlier releases S80 652.050 and S80 656.050 and will be introduced for all future orders.

Customers with valid maintenance can update to the newest version of the firmware.

Please contact [MPI Tech Support](#) for further information.