

# Release note

---

## LinkCom 5 S, LinkCom 5 M, EasyCom 5

Versions:

- LinkCom 5 S, version S80 652.090, June 3., 2020
- LinkCom 5 M, version S80 656.090, June 3., 2020
- EasyCom 5, version S80 654.090, June 3., 2020

### New Features in EasyCom 5 - 654.090

- Data tracing for troubleshooting can now be performed from PrintGuide. Requires PrintGuide version 065.500\*16 or later.

### New Features in LinkCom 5 S - 652.090

- Data tracing for troubleshooting can now be performed from PrintGuide. Requires PrintGuide version 065.500\*16 or later.

### New Features in LinkCom 5 M - 656.090

- Data tracing for troubleshooting can now be performed from PrintGuide. Requires PrintGuide version 065.500\*16 or later.

### Corrections in LinkCom 5 S - 652.090

- PDF417 barcode will not scan when it contains a specific string of characters.
- PDF417 Barcodes containing more than 258 characters do not print.
- Successive FTP prints cause a hang condition.
- IPDS: FS45 transparency in image objects with many (170) picture layers.
- IPDS: FS45 transparency problem in image object.

### Corrections in LinkCom 5 M - 656.090

- IPDS: FS45 transparency in image objects with many (170) picture layers.
- IPDS: FS45 transparency problem in image object.

### Concern

Replaces earlier release S80 65x.080 and will be introduced for all future orders.

Customers with valid maintenance can update to the newest version of the firmware.

Please contact [MPI Tech Support](#) for further information.