

Release note

LinkCom 5 S

Version: S80 652.050*02, November 1, 2016

New features and functionality

This version introduces new and improved features that eases the usability of the LinkCom 5 PrintServer.

- Configuration via Ethernet over USB (OTG port) enables direct configuration of a LinkCom 5 device without a network connection.
- Faster start-up from power on to ready.
- Faster upgrade method.
- Larger runtime memory capacity enables faster job management.

Corrections

IPDS

- Handling of input FS45 encoded images changed to be less memory consuming, in order to be able to handle full page colour images.
- Handling of FS45 images for (IPDS IMAGEENCODE) JPEG output corrected. Caused crash for some FS45 input images.

DCA

- FSL O corrected, an uninitialized variable caused DocOut 7 to crash.
- "PJM EOJ" is now suppressed.

SCS:

- "PJM EOJ" is now suppressed.

Concern

Replaces earlier release S80 652.030 and will be introduced for all future orders.

Customers with valid maintenance can update to the newest version of the firmware.

Please contact [MPI Tech Support](#) for further information.